

Photo 1. View of constructed dock (appx. Sta. 170+00) at end of access canal, looking north



Photo 2. View of access berm at appx. Sta. 170+00, looking south



Photo 3. View of 100' back berm (right side) and back barrier marsh platform (left side), standing at appx. Sta. 170+00 looking east



Photo 4. View of dune back dike, dune platform (right side), and 100' back berm (left side), standing at appx. Sta. 170+00 looking east



Photo 5. View of dune back dike, dune platform (left side), and 100' back berm (right side), standing at appx. Sta. 170+00 looking west



Photo 6. View of camp (appx. Sta. 167+00) and dune platform (~EL. 6.0), standing on dune back dike at appx. Sta. 170+00 looking southwest



Photo 7. View of beach fill and east end of dune platform (Sta. 206+00), looking west



Photo 8. View of constructed dune platform (EL. 8.0) at east end of project (Sta. 206+00), standing on Gulf side dike looking north



Photo 9. View of constructed dune platform (EL. 8.0), standing on dune at east end of project (Sta. 206+00) looking west



Photo 10. View of discharge pipe and beach beyond east end of project, standing on dune at end of project (Sta. 206+00) looking east



Photo 11. View of dune platform (EL. 8.0), back berm, and marsh platform, standing on dune platform at east end of project (Sta. 206+00) looking north



Photo 12. View of constructed dune platform (EL. 8.0), standing on dune at east end of project (Sta. 206+00) looking west



Photo 13. View of discharge pipe at east end of project, looking southeast



Photo 14. . View of dune platform, back berm, and marsh platform, standing on dune platform at appx. Sta. 190+00 looking west



Photo 15. View of marsh platform, standing on dune platform at appx. Sta. 190+00 looking northwest



Photo 16. View of marsh platform, standing on dune platform at appx. Sta. 190+00 looking north



Photo 17. View of beach fill and Gulf side dike, standing on beach at appx. Sta. 190+00 looking west



Photo 18. View of beach fill and Gulf side dike, standing on beach at appx. Sta. 190+00 looking east



Photo 19. View of beach fill (left side) and dune platform (right side), standing on top of dike at appx. Sta. 173+00 looking west



Photo 20. View of beach fill (right side) and dune platform (left side), standing on top of dike at appx. Sta. 173+00 looking east



Photo 21. View of front and side dikes at west end of project at the end of Canal 19, standing Gulf side of project at appx. Sta. 95+00 looking northwest



Photo 22. View of front and back dikes at west end of project at the end of Canal 19, standing Gulf side of project at appx. Sta. 95+00 looking north



Photo 23. View of front and side dikes at west end of project at the end of Canal 19, standing on top of front dike at appx. Sta. 95+00 looking west



Photo 24. View of front dike at west end of project at the end of Canal 19, standing on top of dike at appx. Sta. 95+00 looking east



Photo 25. View of beach fill, standing on top of existing rock shoreline protection at appx. Sta. 100+00 looking east



Photo 26. View of dune platform back dike, standing inside dune platform area at appx. Sta. 160+00 looking east



Photo 27. View of dune platform back dike, standing inside dune platform area at appx. Sta. 160+00 looking west



Photo 28. View of dune platform (material to ~EL. 6.0), standing on top of dune material at appx. Sta. 164+00 looking east



Photo 29. View of end of dredged material discharge pipe at appx. Sta. 171+00 (dredge demobilized due to storms in Gulf)



Photo 30. View of access berm (appx. Sta. 170+00), standing on top of dune back dike looking north



Photo 31. View of dune back dike, dune platform material (right side), and 100' back berm (left side), standing at appx. Sta. 171+00 looking east



Photo 32. View of 100' back berm (foreground) and back barrier marsh platform (background) on east side of access berm, standing at appx. Sta. 171+00 looking north



Photo 33. View of 100' back berm (foreground) and back marsh platform (background) on west side of access berm, standing at appx. Sta. 170+00 looking northwest



Photo 34. View of back marsh platform area on west side of access berm, standing at appx. Sta. 170+00 looking northwest



Photo 35. View of breach repair in back dike at appx. Sta. 178+00, looking east



Photo 36. View of breach repair in back dike at appx. Sta. 178+00, looking east



Photo 37. View of back barrier marsh platform, standing on back dike at appx. Sta. 177+00 looking south



Photo 38. View of constructed dock (appx. Sta. 170+00) at end of access canal, looking west